


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10393	Main Street: LIMA_AV	Cross Street: ROZZELLES_FERRY_RD	Location: S
ADA ID: AB4749B95012	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 21.25	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
 Street 1 Name ROZZELLES FERRY RD Stop Condition-Street 2 None Street 2 Name LIMA AV Stop Condition-Street 1 StopSign	Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3	Total Cost: \$ 3200.00			
			Compliance	Description	Data
			Compliance	Description	Data
			N/A	Ramp Length (in)	77.0
			No	Ramp Width (in)	36.0
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	7.8
				X Walk 1 X Slope (%)	2.0
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	7.0
				Road X Slope (%)	5.3
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

