## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A	Main Street: ARDREY_KELL_DR			Street:	N/A	Location:	NE		
ADA ID: AB5945A87739	Ramp Ty	ype: PerpDiag	Initial P	itial Pass/Fail: Fail Overall Compliance: No				Severity Score:	35
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	-	Possible Solutions:		Compliance Description		Data Compliance Description			Data
Charles of		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	82.0	No	Ramp Slope (%)	14.4
		Two New Directional Ramps or		No	Ramp Width (in)	44.0	No	Ramp XSlope (%)	2.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	and the second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	ED	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
727		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second secon	Line and the second sec			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
CARDon -	6.			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the second	L SA	R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
e de la companya de l	A AV att				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	0.9
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	0.4
Street 2 Name	ARDREY KELL RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.1	N/A	Clear Space?	N/A
					Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
l						N/A			N/A

es Surface Condition? (G/P)

Good

