cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15185Main Street: ARDSLEY_RDCross Street: PROVIDENCE_RDLocation:SWADA ID: AB888BC53F04Ramp Type: PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:21.25Codes/Mitigation Info/Possible SolutionField Measurements/Component CompliancePossible Solutions:Remove & Replace Curb Ramp WithN/ARamp Length (in)67.0NoRamp Slope (%)8.9Two New Directional Ramps or Equivalent.N/AFlare Type LTN/AN/AFlare Type RTN/AN/AFlare Slope LT (%)N/AFlare Slope RT (%)N/AN/AFlare Slope RT (%)N/AN/AFlare Traversable LT?N/AFlare Traversable RT?N/AN/AFlare Traversable RT?N/A
Field Measurements/Component Compliance Field Measurements/Component Compliance Description Data Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. N/A Ramp Length (in) 67.0 No Ramp Slope (%) 8.9 N/A Flare Type LT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) 1.7 N/A Flare Traversable LT? N/A Flare Traversable RT? N/A
Possible Solutions:Compliance DescriptionDataCompliance DescriptionDataN/ARamove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.N/ARamp Length (in)67.0NoRamp Slope (%)8.9N/AFlare Type LTN/AN/AFlare Type RTN/AN/AFlare Slope LT (%)N/AN/AFlare Slope RT (%)N/AN/AFlare Traversable LT?N/AN/AFlare Traversable RT?N/A
N/ARamp Length (in)67.0NoRamp Slope (%)8.9N/AN/ARamp Width (in)39.0YesRamp XSlope (%)1.7N/AFlare Type LTN/AN/AFlare Type RTN/AN/AFlare Slope LT (%)N/AN/AFlare Slope RT (%)N/AN/AFlare Traversable LT?N/AN/AFlare Traversable RT?N/A
Image: Second
Image: Second state of the second s
N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A
N/A Landing Length (in) N/A DWS Provided? N/A
Surveyor Notes: N/A Landing Width (in) N/A N/A DWS Contrast? N/A
N/A N/A DWS Length (in) N/A
N/A Landing X Slope (%) N/A DWS Full Width? N/A
N/A Landing Curb? (Y/N) N/A DWS Offset (in) N/A
N/A Shared Landing? N/A
PROW/ADA: N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A
Not Found, R304.5.1, R304.2.2 N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A
N/A Painted X Walk1? No N/A Painted X Walk2? No
X Walk 1 Direction To E X Walk 2 Direction To N
N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A
Street 1 Name PROVIDENCE RD X Walk 1 Slope (%) 1.2 X Walk 2 Slope (%) 0.7
Stop Condition-Street 2 None X Walk 1 X Slope (%) 0.6 X Walk 2 X Slope (%) 2.3
Street 2 Name ARDSLEY RD N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A
Stop Condition-Street 1 StopSign Road Slope (%) 0.7 N/A Clear Space? N/A
Road X Slope (%) 0.8 N/A Clear Space to XWalk (in) N/A
N/A Any Obstructions? N/A N/A Storm Grate/Utility Hazard? N/A
Total Cost: \$ 3200.00 Obstruction Type Storm Grate/Utility Type
N/A N/A
Yes Surface Condition? (G/P) Good

