


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10011027	Main Street: BLACKHAWK_RD	Cross Street: N/A	Location: S
ADA ID: AB8C92C56282	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 22.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	56.0
	Remove & Replace Gutter.		Yes	Ramp Width (in)	97.5
			N/A	Flare Type LT	None
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			Yes	Landing Length (in)	60.0
			Yes	Landing Width (in)	98.0
			No	Landing Slope (%)	3.4
			Yes	Landing X Slope (%)	1.0
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2-Perp, R304.3.2-Para, R305, R302.7, R302.7.2, R304.5.4</p>			N/A	Landing Curb? (Y/N)	No
			N/A	Shared Landing?	No
			No	Gutter Ponding?	Yes
			No	Gutter Lip Ht (in)	0.5
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To N
			N/A	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	2.4
				X Walk 1 X Slope (%)	1.4
			N/A	Ramp inside XWalk1?	N/A
<p>Street 1 Name</p> <p>Stop Condition-Street 2</p> <p>Street 2 Name</p> <p>Stop Condition-Street 1</p>			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
			N/A		
			Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 2600.00			

