cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 44268 Main Street: ISAAC_HUNTER_DR Cross Street: EMILY_HOPE_DR Location: S									
Intersection ID: 44268 Main St	Main Street: ISAAC_HUNTER_DR		street:	EWILY_HOPE_DR	Location:	S			
ADA ID: AB90C8B5BF7A Ramp T	5BF7A Ramp Type: PerpDiag		ass/Fa	ail: Fail Overall	Severity Score:	33.75			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Compliance Description			Data Compliance Description		Data	
	Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.7	
	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	45.0	No	Ramp XSlope (%)	7.6	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	1		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
a de la compañía de la			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name EMILY HOPE DR				X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	1.2	
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	5.6	
Street 2 Name ISAAC HUNTER DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 None				Road Slope (%)	4.9	N/A	Clear Space?	N/A	
				Road X Slope (%)	2.9	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

