

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

29.0

62.0

10.1 4.7 5.0 1.4

N/A N/A

N/A N/A N/A

N/A

N/A N/A

N/A

N/A

No

To E

N/A 3.0 1.4

N/A

N/A

N/A

N/A

N/A

N/A

N/A

9.7

Good

Main Street: WESTINGHOUSE BV **Cross Street: N/A** Location: Intersection ID: 10041443 NW **ADA ID: ABD21CC30268** Ramp Type: Combination1Diag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 0

Codes/Mitigation Info/Possible Solution

Possible Solutions:

Field Measurements/Component Compliance



Street 1 Name None **WESTINGHOUSE BV** Stop Condition-Street 1 Street 2 Name StopSign Stop Condition-Street 2 N/A

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A

Not Found, R304.5.3, R304.3.2

Total Cost:

PROW/ADA:

Compliance Description Data Compliance Description				
N/A	Ramp Length LT (in)	40.0	N/A	Ramp Length RT (in)
Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)
Yes	Ramp Slope LT (%)	6.4	No	Ramp Slope RT (%)
No	Ramp XSlope LT (%)	2.5	No	Ramp XSlope RT (%)
N/A	Ramp Length (in)	46.0	Yes	Ramp Slope (%)
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)
	. ,			,
N/A	Flare Type LT	N/A	N/A	Flare Type RT
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?
N/A	Landing Length (in)	N/A	N/A	DWS Provided?
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)
N/A	Shared Landing?	N/A		
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?
	X Walk 1 Direction	To S		X Walk 2 Direction
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)
	X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)
	X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?

N/A

N/A

N/A

Yes

1.1

8.0

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)







Road Slope (%)

Road X Slope (%)

3200.00