

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 13482 Main Street: ARNOLD DR Cross Street: CENTRAL\_AV Location: NW **Overall Compliance: No** ADA ID: ABE3E3B9AC15 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 10

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name ARNOLD DR Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3

Total Cost: 1850.00

Field Measurements/Component Compliance		
Compliance Description Data Com	pliance Description	Data
N/A Ramp Length (in) 25.0 Yes	Ramp Slope (%)	7.7
No Ramp Width (in) 47.0 No	Ramp XSlope (%)	3.8
N/A Flare Type LT N/A N/A	Flare Type RT	N/A
N/A Flare Slope LT (%) N/A N/A	Flare Slope RT (%)	N/A
N/A Flare Traversable LT? N/A N/A	Flare Traversable RT?	N/A
N/A Landing Length (in) N/A N/A	DWS Provided?	N/A
N/A Landing Width (in) N/A N/A	DWS Contrast?	N/A
N/A Landing Slope (%) N/A N/A	DWS Length (in)	N/A
N/A Landing X Slope (%) N/A N/A	DWS Full Width?	N/A
N/A Landing Curb? (Y/N) N/A N/A	DWS Offset (in)	N/A
N/A Shared Landing? N/A		
N/A Gutter Ponding? N/A N/A	Gutter Slope (%)	N/A
N/A Gutter Lip Ht (in) N/A N/A	Gutter X Slope (%)	N/A
N/A Painted X Walk1? No N/A	Painted X Walk2?	N/A
X Walk 1 Direction To SE	X Walk 2 Direction	N/A
N/A X Walk 1 Width (in) N/A N/A	X Walk 2 Width (in)	N/A
X Walk 1 Slope (%) <b>6.0</b>	X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%) 2.5	X Walk 2 X Slope (%)	N/A
N/A Ramp inside XWalk1? N/A N/A	Ramp inside XWalk2?	N/A
Road Slope (%) N/A N/A	Clear Space?	N/A
Road X Slope (%) N/A N/A	Clear Space to XWalk (in)	N/A
N/A Any Obstructions? N/A N/A	Storm Grate/Utility Hazard?	N/A
Obstruction Type	Storm Grate/Utility Type	
N/A		N/A
Yes	Surface Condition? (G/P)	Good





