


# Access Compliance Report

## Public Rights-of-Way (Curb Ramps)

Intersection ID: 22508		Main Street: KRISLYN_WOODS_PL	Cross Street: SEASCAPE_LN	Location:	SW
ADA ID: AC14556E9109		Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 10
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
		Possible Solutions:	Compliance	Description	Data
		Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	74.0
<p>Surveyor Notes:</p> <p>N/A</p>			No	Ramp Width (in)	46.0
			Yes	Ramp Slope (%)	3.3
<p>PROW/ADA:</p> <p>R304.5.1, R304.5.3</p>			No	Ramp XSlope (%)	3.2
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	0.0
			N/A	Landing Width (in)	0.0
			N/A	Landing Slope (%)	0.0
			N/A	Landing X Slope (%)	0.0
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	0.0
			N/A	Gutter Lip Ht (in)	0.0
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To SE
				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	1.4
				X Walk 1 X Slope (%)	0.2
			N/A	Ramp inside XWalk1?	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	2.9
<p>Street 1 Name</p> <p>Stop Condition-Street 1</p> <p>Street 2 Name</p> <p>Stop Condition-Street 2</p>		<p>SEASCAPE LN</p> <p>StopSign</p> <p>N/A</p> <p>N/A</p>	<p>Total Cost: \$ 1600.00</p>		

