cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10035065 Main Street: PROVIDENCE_RD Cross Street: N/A								Location:	NW
ADA ID: AC1C5230ABCF		Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				
									22.3
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ram	•	N/A	Ramp Length (in)	91.0	No	Ramp Slope (%)	10.6
		Two New Directional Ramps or Equivalent.	or	No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	2.9
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Common 12	A day street			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A CARLON CONTRACTOR	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E.		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
No. Contraction				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
" BER	6. A			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Serve .		6		N/A	Shared Landing?	N/A			
0	C	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and a second	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
- Aly m				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	0.9
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	3.3
Street 2 Name	PROVIDENCE RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.8	N/A	Clear Space?	N/A
					Road X Slope (%)	5.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
1						N/A			IN/A

Yes Surface Condition? (G/P) Good

