cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| | | - | | | | | | | |
|---|--------------------|------------------------------|---------|---|-------------------------------------|------------|-----------------------------|-----------------------------|-------|
| Intersection ID: 21678 | Main Str | Main Street: GONEAWAY_RD | | | Cross Street: HUNTINGTOWNE_FARMS_LN | | | | SW |
| ADA ID: AC2123C83A05 | Ramp Ty | Ramp Type: PerpDiag | | | ail: Fail Overall (| ce: N | o Severity Score: | 8.75 | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| A CONTRACT OF THE OWNER | | Possible Solutions: | | | | | Data Compliance Description | | |
| | AL OF | Remove & Replace Curb Ramp \ | Nith | N/A | Ramp Length (in) | 57.0 | Yes | Ramp Slope (%) | 7.4 |
| Change The Art of the | the and the second | Two New Directional Ramps or | | No | Ramp Width (in) | 41.0 | Yes | Ramp XSlope (%) | 0.4 |
| Carley And Marine | L/ 1 m | Equivalent. | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | The St | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| Call States | North A | Surveyor Notes: | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | A BOARD AND | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| A CONTRACTOR OF CONTRACTOR | | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| A A A A A A A A A A A A A A A A A A A | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | 102 | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | No. | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| A ALL A AND A | | | N/A | Shared Landing? | N/A | | | | |
| | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | Not Found, R304.5.1 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | COLOR AND AND | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| A | and the second | | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | To NW |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name HUNTINGTOWNE FARMS LN | | | | | X Walk 1 Slope (%) | 4.6 | | X Walk 2 Slope (%) | 3.1 |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 2.2 | | X Walk 2 X Slope (%) | 4.0 |
| Street 2 Name | GONEAWAY RD | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | StopSign | | | | Road Slope (%) | 2.4 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 5.0 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | 0.0 N/A | | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | Ψ. | | | | N/A | 1 | | N/A |
| | | | | | | 11/A | | | 11/2 |

