


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 5716	Main Street: SPANISH_MOSS_LN	Cross Street: WILD_ORCHID_CT	Location: E
ADA ID: AC72906C1754	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 8.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance																																																																																																																																																														
 <p>Possible Solutions:</p> <p>Remove & Replace Entire Ramp.</p> <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1</p>			<table> <thead> <tr> <th>Compliance</th><th>Description</th><th>Data</th><th>Compliance</th><th>Description</th><th>Data</th></tr> </thead> <tbody> <tr> <td>N/A</td><td>Ramp Length (in)</td><td>97.0</td><td>Yes</td><td>Ramp Slope (%)</td><td>5.2</td></tr> <tr> <td>No</td><td>Ramp Width (in)</td><td>36.0</td><td>Yes</td><td>Ramp XSlope (%)</td><td>0.7</td></tr> <tr> <td>N/A</td><td>Flare Type LT</td><td>N/A</td><td>N/A</td><td>Flare Type RT</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Flare Slope LT (%)</td><td>N/A</td><td>N/A</td><td>Flare Slope RT (%)</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Flare Traversable LT?</td><td>N/A</td><td>N/A</td><td>Flare Traversable RT?</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Landing Length (in)</td><td>N/A</td><td>N/A</td><td>DWS Provided?</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Landing Width (in)</td><td>N/A</td><td>N/A</td><td>DWS Contrast?</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Landing Slope (%)</td><td>N/A</td><td>N/A</td><td>DWS Length (in)</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Landing X Slope (%)</td><td>N/A</td><td>N/A</td><td>DWS Full Width?</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Landing Curb? (Y/N)</td><td>N/A</td><td>N/A</td><td>DWS Offset (in)</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Shared Landing?</td><td>N/A</td><td></td><td></td><td></td></tr> <tr> <td>N/A</td><td>Gutter Ponding?</td><td>N/A</td><td>N/A</td><td>Gutter Slope (%)</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Gutter Lip Ht (in)</td><td>N/A</td><td>N/A</td><td>Gutter X Slope (%)</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Painted X Walk1?</td><td>No</td><td>N/A</td><td>Painted X Walk2?</td><td>N/A</td></tr> <tr> <td></td><td>X Walk 1 Direction</td><td>To W</td><td></td><td>X Walk 2 Direction</td><td>N/A</td></tr> <tr> <td>N/A</td><td>X Walk 1 Width (in)</td><td>N/A</td><td>N/A</td><td>X Walk 2 Width (in)</td><td>N/A</td></tr> <tr> <td></td><td>X Walk 1 Slope (%)</td><td>2.4</td><td></td><td>X Walk 2 Slope (%)</td><td>N/A</td></tr> <tr> <td></td><td>X Walk 1 X Slope (%)</td><td>3.0</td><td></td><td>X Walk 2 X Slope (%)</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Ramp inside XWalk1?</td><td>N/A</td><td>N/A</td><td>Ramp inside XWalk2?</td><td>N/A</td></tr> <tr> <td></td><td>Road Slope (%)</td><td>N/A</td><td>N/A</td><td>Clear Space?</td><td>N/A</td></tr> <tr> <td></td><td>Road X Slope (%)</td><td>N/A</td><td>N/A</td><td>Clear Space to XWalk (in)</td><td>N/A</td></tr> <tr> <td>N/A</td><td>Any Obstructions?</td><td>N/A</td><td>N/A</td><td>Storm Grate/Utility Hazard?</td><td>N/A</td></tr> <tr> <td></td><td>Obstruction Type</td><td></td><td></td><td>Storm Grate/Utility Type</td><td></td></tr> <tr> <td></td><td></td><td></td><td>N/A</td><td></td><td>N/A</td></tr> <tr> <td></td><td></td><td></td><td>Yes</td><td>Surface Condition? (G/P)</td><td>Good</td></tr> </tbody> </table>			Compliance	Description	Data	Compliance	Description	Data	N/A	Ramp Length (in)	97.0	Yes	Ramp Slope (%)	5.2	No	Ramp Width (in)	36.0	Yes	Ramp XSlope (%)	0.7	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	N/A	Shared Landing?	N/A				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		X Walk 1 Direction	To W		X Walk 2 Direction	N/A	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A		X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		Road Slope (%)	N/A	N/A	Clear Space?	N/A		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		Obstruction Type			Storm Grate/Utility Type					N/A		N/A				Yes	Surface Condition? (G/P)	Good
Compliance	Description	Data	Compliance	Description	Data																																																																																																																																																												
N/A	Ramp Length (in)	97.0	Yes	Ramp Slope (%)	5.2																																																																																																																																																												
No	Ramp Width (in)	36.0	Yes	Ramp XSlope (%)	0.7																																																																																																																																																												
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A																																																																																																																																																												
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A																																																																																																																																																												
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A																																																																																																																																																												
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A																																																																																																																																																												
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A																																																																																																																																																												
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A																																																																																																																																																												
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A																																																																																																																																																												
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A																																																																																																																																																												
N/A	Shared Landing?	N/A																																																																																																																																																															
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A																																																																																																																																																												
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A																																																																																																																																																												
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A																																																																																																																																																												
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A																																																																																																																																																												
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A																																																																																																																																																												
	X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A																																																																																																																																																												
	X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A																																																																																																																																																												
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A																																																																																																																																																												
	Road Slope (%)	N/A	N/A	Clear Space?	N/A																																																																																																																																																												
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A																																																																																																																																																												
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A																																																																																																																																																												
	Obstruction Type			Storm Grate/Utility Type																																																																																																																																																													
			N/A		N/A																																																																																																																																																												
			Yes	Surface Condition? (G/P)	Good																																																																																																																																																												
<p>Street 1 Name WILD ORCHID CT</p> <p>Stop Condition-Street 2 StopSign</p> <p>Street 2 Name N/A</p> <p>Stop Condition-Street 1 N/A</p>			<p>Total Cost: \$ 1850.00</p>																																																																																																																																																														

