

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 19463 Main Street: BARCLAY DOWNS DR Cross Street: SAYRE_RD Location: Ε ADA ID: AC8AE50A49AF Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

Compliance Description

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data Compliance Description



Stre Sto Stre Sto

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2

| CALLES ! |
|------------------|
| BARCLAY DOWNS DR |
| StopSign |
| SAYRE RD |
| StopSign |
| |
| |

Total Cost: 3200.00

| N/A | Ramp Length (in) | 49.0 | No | Ramp Slope (%) | 8.5 |
|-----|-----------------------|------|-----|-----------------------------|-------|
| Yes | Ramp Width (in) | 49.0 | Yes | Ramp XSlope (%) | 1.8 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | Yes |
| | X Walk 1 Direction | To N | | X Walk 2 Direction | To SW |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | 95.0 |
| | X Walk 1 Slope (%) | 0.7 | | X Walk 2 Slope (%) | 5.0 |
| | X Walk 1 X Slope (%) | 2.4 | | X Walk 2 X Slope (%) | 1.1 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | Yes |
| | Road Slope (%) | 1.4 | N/A | Clear Space? | N/A |
| | Road X Slope (%) | 3.6 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | | | |





