

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47432 Main Street: LALEX_LN Cross Street: E WOODLAWN RD Location: SE

ADA ID: ACAF25529311 Ramp Type: ParaDiag Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name E WOODLAWN RD
Stop Condition-Street 1 None
Street 2 Name LALEX LN
Stop Condition-Street 2 StopSign

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent. Remove & Replace
Gutter.

Surveyor Notes:

MEDIAN ACROSS E WOODLAWN RD, RT RP < 5%

PROW/ADA:

Not Found, R304.2.1, R304.5.3

Total Cost: \$ 3950.00

Compliance Description Data		Compliance Description		Data	
N/A	Ramp Length LT (in)	43.0	N/A	Ramp Length RT (in)	59.0
Yes	Ramp Width LT (in)	58.0	Yes	Ramp Width RT (in)	59.0
Yes	Ramp Slope LT (%)	5.1	Yes	Ramp Slope RT (%)	0.9
Yes	Ramp XSlope LT (%)	1.4	Yes	Ramp XSlope RT (%)	1.5
Yes	Landing Length (in)	59.0	Yes	DWS Provided?	Yes
No	Landing Width (in)	38.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	1.8	Yes	DWS Length (in)	24.0
No	Landing X Slope (%)	4.9	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	2.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.4
Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	3.7
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To N		X Walk 2 Direction	To W
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.0		X Walk 2 Slope (%)	2.2
	X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	1.9
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.6	N/A	Clear Space?	Yes
	Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Replace Curb Siloppe (%)		14.3





