


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9492	Main Street: CORDOVA_LN	Cross Street: DELTA_LAKE_DR	Location: NE
ADA ID: AD17706BA103	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	168.0
			Yes	Ramp Width LT (in)	59.5
			No	Ramp Slope LT (%)	11.3
			Yes	Ramp XSlope LT (%)	0.3
			N/A	Ramp Length (in)	43.5
			Yes	Ramp Width (in)	58.0
	Surveyor Notes:		N/A	Flare Type LT	N/A
	RAMP LIP 2.0		N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
	PROW/ADA:		N/A	Landing Length (in)	N/A
	Not Found, R304.5.3, R304.3.2		N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	0.5
			N/A	Painted X Walk1?	No
				X Walk 1 Direction	To S
<div> <div>Street 1 Name</div> <div>Stop Condition-Street 1</div> <div>Street 2 Name</div> <div>Stop Condition-Street 2</div> </div> <div> <div>None</div> <div>DELTA LAKE DR</div> <div>N/A</div> <div>N/A</div> </div>				X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	4.7
				X Walk 1 X Slope (%)	3.9
			N/A	Ramp inside XWalk1?	N/A
				Road Slope (%)	3.9
				Road X Slope (%)	4.7
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	N/A
	Total Cost:	\$ 1800.00		Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	N/A
				Surface Condition? (G/P)	Good
				Curb Slope (%)	32.5