


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 10252		Main Street: MATHIS_DR		Cross Street: ROGERS_ST		Location: E											
ADA ID: AD17C17B1271		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 2.5									
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance													
<div></div> <div>Possible Solutions:</div> <div>Remove & Replace Entire Ramp.</div> <div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>Not Found, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305.1.4, R305.2</div> <div>Street 1 Name</div> <div>MATHIS DR</div> <div>Stop Condition-Street 1</div> <div>StopSign</div> <div>Street 2 Name</div> <div>N/A</div> <div>Stop Condition-Street 2</div> <div>N/A</div> <div>Total Cost:</div> <div>\$</div> <div>1600.00</div>				Compliance		Description		Data		Compliance		Description		Data			
				N/A		Ramp Length (in)		127.0		Yes		Grade Break?		Yes			
				Yes		Ramp Width (in)		58.5		No		Grade Break Slope (%)		5.6			
				Yes		Ramp Slope (%)		6.4		Yes		Grade Break XSlope (%)		1.0			
				Yes		Ramp XSlope (%)		1.0									
				Yes		Flare Type LT		N/A		Yes		Flare Type RT		N/A			
				N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		N/A			
				N/A		Flare Traversable LT?		No		N/A		Flare Traversable RT?		No			
				No		Landing Length (in)		45.0		Yes		DWS Provided?		Yes			
				Yes		Landing Width (in)		60.0		Yes		DWS Contrast?		Yes			
				No		Landing Slope (%)		2.9		Yes		DWS Length (in)		24.0			
				Yes		Landing X Slope (%)		1.4		No		DWS Full Width?		No			
				N/A		Landing Curb? (Y/N)		N/A		No		DWS Offset LT (in)		5.0			
				N/A		Shared Landing?		No		Yes		DWS Offset RT (in)		31.0			
				Yes		Gutter Ponding?		No		Yes		Gutter Slope (%)		2.6			
				Yes		Gutter Lip Ht (in)		0.0		Yes		Gutter X Slope (%)		1.2			
				N/A		Painted X Walk1?		No				Road Slope (%)		1.7			
						X Walk 1 Direction		To NW				Road X Slope (%)		3.2			
						X Walk 1 Width (in)		N/A				Clear Space?		Yes			
						X Walk 1 Slope (%)		1.7		N/A		Clear Space to XWalk (in)		N/A			
						X Walk 1 X Slope (%)		3.2		Yes		Storm Grate/Utility Hazard?		No			
				N/A		Ramp inside XWalk1?		N/A				Storm Grate/Utility Type					
				Yes		Any Obstructions?		No						N/A			
						Obstruction Type				Yes		Surface Condition? (G/P)		Good			
										N/A		No		Curb Slope (%)		8.6	

