


Access Compliance Report Public Rights-of-Way (Curb Ramps)




Intersection ID: 10020275Main Street: AYRSLEY_TOWN_BVCross Street: N/ALocation:SWADA ID: ADA18105DD88Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name ENTRANCE
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:	c		
Remove & Replace Entire Ramp.			
•	N		
	N/		
	N		
	N		
	N		
Surveyor Notes:	N		
N/A	N		
	N		
	N		
	N		
PROW/ADA:	N		
Not Found, R304.5.1, R304.2.2,	N/		
R304.5.3	N		
	N		
	N		





Total Cost:



1850.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	63.0	No	Ramp Slope (%)	8.7	
No	Ramp Width (in)	45.0	No	Ramp XSlope (%)	3.4	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	