

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: MILLENNIUM_AV Cross Street: CITY_PARK_DR Location: SE

ADA ID: ADB20DA5FAAF Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 1

StopSign
Street 2 Name

N/A
Stop Condition-Street 2

N/A

Remove & Replace Entire Ramp.

Surveyor Notes:
N/A

PROW/ADA:
R304.2.2

Total Cost: \$ 1600.00

| Field Measurements/Component Compliance | | | | | |
|---|-----------------------|-------|------|-----------------------------|------|
| Compliance Description | | Data | Comp | liance Description | Data |
| N/A | Ramp Length (in) | 110.0 | N/A | Grade Break? | N/A |
| Yes | Ramp Width (in) | 70.0 | N/A | Grade Break Slope (%) | 0.0 |
| No | Ramp Slope (%) | 9.1 | N/A | Grade Break XSlope (%) | 0.0 |
| Yes | Ramp XSlope (%) | 0.1 | | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A |
| N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A |
| N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | Yes | | Road Slope (%) | 2.9 |
| | X Walk 1 Direction | To W | | Road X Slope (%) | 1.4 |
| | X Walk 1 Width (in) | 84.0 | | Clear Space? | N/A |
| | X Walk 1 Slope (%) | 2.9 | N/A | Clear Space to XWalk (in) | N/A |
| | X Walk 1 X Slope (%) | 1.4 | N/A | Storm Grate/Utility Hazard? | N/A |
| N/A | Ramp inside XWalk1? | Yes | | Storm Grate/Utility Type | |
| N/A | Any Obstructions? | N/A | | | N/A |
| | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | N/A | N/A | Curb Slope (%) | 0.5 |
| | | | | | |





