cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7185	tersection ID: 7185 Main Street: S_I-85_EXIT_41_RA			Cross Street: W_SUGAR_CREEK_RD				Location:	NW
ADA ID: ADCED15AC3B	ID: ADCED15AC3B4 Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						Compliance Description	
		Remove & Replace Curb R	nn With	N/A	Ramp Length (in)	48.0	1	Ramp Slope (%)	<u>Data</u> 8.7
		Two New Directional Ramps	•	No	Ramp Width (in)	47.5		Ramp XSlope (%)	0.2
and state ?		Equivalent.		N/A	Flare Type LT	N/A		Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
2 - Conta				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
ml. All	BIL IS-	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
1 Star Ale		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
7.000	RA Z	N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
BLEBLEAU AND BE BE BE PROW/ADA:				N/A	Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		DWG Oliset (III)	11/2
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		•		0	N/A	N/A	,		
Not Found, R304.5.1, R304.2.2			.2	N/A	Gutter Lip Ht (in)			Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	115.0	N/A	X Walk 2 Width (in)	113.0
Street 1 Name	S I-85 EXIT 41 RA				X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	1.0
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	1.5
Street 2 Name	W SUGAR CREEK RD			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	Signal				Road Slope (%)	0.2	N/A	Clear Space?	N/A
					Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
1									

s Surface Condition? (G/P)

Good

