



Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 7008	Main Street: MCALLISTER_DR	Cross Street: MERRILL_PL	Location: SE
ADA ID: ADD36BDE2C59	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance															
			Possible Solutions:			Compliance			Description			Data						
			Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			N/A			Ramp Length (in)			32.5						
			Surveyor Notes:			No			Ramp Width (in)			44.0						
			N/A			N/A			Flare Type LT			N/A						
<p>Street 1 Name</p> <p>Stop Condition-Street 2</p> <p>Street 2 Name</p> <p>Stop Condition-Street 1</p>			PROW/ADA:			N/A			N/A			Flare Slope LT (%)			N/A			
			Not Found, R304.5.1			N/A			N/A			Flare Traversable LT?			N/A			
<p>Total Cost:</p>									N/A			Landing Length (in)			N/A			
									N/A			Landing Width (in)			N/A			
									N/A			Landing Slope (%)			N/A			
									N/A			Landing X Slope (%)			N/A			
									N/A			Landing Curb? (Y/N)			N/A			
									N/A			Shared Landing?			N/A			
									N/A			Gutter Ponding?			N/A			
									N/A			Gutter Lip Ht (in)			N/A			
									N/A			Painted X Walk1?			No			
									To N			X Walk 2 Direction			To W			
									N/A			X Walk 1 Width (in)			N/A			
												X Walk 2 Width (in)			N/A			
												X Walk 1 Slope (%)			4.4			
												X Walk 2 Slope (%)			4.6			
												X Walk 1 X Slope (%)			6.3			
												X Walk 2 X Slope (%)			4.6			
									N/A			Ramp inside XWalk1?			N/A			
									N/A			Ramp inside XWalk2?			N/A			
									0.9			Clear Space?			N/A			
									9.0			Clear Space to XWalk (in)			N/A			
									N/A			Any Obstructions?			N/A			
												Storm Grate/Utility Hazard?			N/A			
												Obstruction Type						
									N/A			Storm Grate/Utility Type			N/A			
												Yes			Surface Condition? (G/P)		Good	

