

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 15905 Main Street: PEMBROKE\_AV Cross Street: QUEENS\_RD Location: SW Ramp Type: Directional1 **Severity Score:** ADA ID: ADF9C4EA799E Initial Pass/Fail: Fail **Overall Compliance: No** 12.5

**Codes/Mitigation Info/Possible Solution** 



**PEMBROKE AV** Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Surveyor Notes:					
N/A					
PROW/ADA:					
R304.5.3					

Total Cost: 1600.00

Field Measurements/Component Compliance							
	Compliance Description		Data	Compliance Description		Data	
	N/A	Ramp Length (in)	125.0	N/A	Grade Break?	N/A	
	Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
	Yes	Ramp Slope (%)	2.9	N/A	Grade Break XSlope (%)	0.0	
	No	Ramp XSlope (%)	5.5				
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	No		Road Slope (%)	3.1	
		X Walk 1 Direction	To N		Road X Slope (%)	4.9	
		X Walk 1 Width (in)	N/A		Clear Space?	N/A	
		X Walk 1 Slope (%)	3.1	N/A	Clear Space to XWalk (in)	N/A	
		X Walk 1 X Slope (%)	4.9	N/A	Storm Grate/Utility Hazard?	N/A	
	N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
	N/A	Any Obstructions?	N/A			N/A	
		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
			N/A	N/A	Curb Slope (%)	11.9	





