

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10431 Main Street: ASHLEY RD **Cross Street: SCOTT FUTRELL DR** Location: NW **ADA ID: AE5295B4D87A** Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

## **Codes/Mitigation Info/Possible Solution**



**SAM FURTRELL DR** Street 1 Name Signal Stop Condition-Street 2 Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	_							
Remove & Replace Entire Ramp.								
Surveyor Notes:								
N/A								
1071								
PROW/ADA:								
R304.2.2								

A COLUMN	-4		
		mact the	$\parallel$
			#
			#-
	14		
	1		

Total Cost:



1850.00

Field Measurements/Component Compliance									
Comp	liance Description	Data	Comp	liance Description	Data				
N/A	Ramp Length (in)	83.5	No	Ramp Slope (%)	9.2				
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.1				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A				
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A				
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A				
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A				
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A				
N/A	X Walk 1 Width (in)	114.0	N/A	X Walk 2 Width (in)	N/A				
	X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	N/A				
	X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A				
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A				
	Road Slope (%)	N/A	N/A	Clear Space?	N/A				
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A				
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
	Obstruction Type			Storm Grate/Utility Type					
		N/A			N/A				
VIII.			Yes	Surface Condition? (G/P)	Good				