

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24904 Main Street: PROVIDENCE_RD Cross Street: PINEVILLE-MATTHEWS_RD Location: SE

ADA ID: AE6D7EA03CFB Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 22.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name PROVIDENCE RD
Stop Condition-Street 2 YieldSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	59.0	No	Ramp	Slope (%)	10.1
No	Ramp Width (in)	45.0	No	Ramp	XSlope (%)	3.3
N/A	Flare Type LT	N/A	N/A	Flare	Гуре RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare S	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS I	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS (Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS I	_ength (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS I	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS (Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painte	d X Walk2?	N/A
	X Walk 1 Direction	To NW		X Wall	c 2 Direction	N/A
N/A	X Walk 1 Width (in)	114.0	N/A	X Wall	c 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.2		X Wall	< 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.0		X Wall	< 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfac	e Condition? (G/P)	Good
	To and the same of					





