

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

46.0

45.5

13.8

9.8

12.0

9.9

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 10640Main Street:MARTIN_STCross Street:WAKE_STLocation:SWADA ID: AE76727EE29DRamp Type:Combination1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:85

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

No

No

No

N/A

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Total Cost:

Field Measurements/Component Compliance

N/A

No

No

No

No

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

57.0

47.0

17.4

5.1

48.0

26.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A



Street 1 Name
StopSign
Stop Condition-Street 1
WAKE ST
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:					
Remove & Replace Entire Ramp.					
Surveyor Notes:					
N/A					
N/A					
PROW/ADA:					
R304.5.1, R304.5.1, R304.2.2,					
R304.5.3, R304.3.2					





1800.00

N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	16.2		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
helic Land			N/A	Any Obstruction?	N/A
				Obstruction Type	
					N/A
			N/A Storm	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	14,71
1					N/A
1			Yes	Surface Condition? (G/P)	Good
				Curb Slope (%)	3.4