

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

58.0

60.0

11.3

3.2

0.5

2.9

N/A

Main Street: ROZZELLES FERRY RD Intersection ID: 52125 **Cross Street: VALLEYDALE RD** Location: NW **Overall Compliance: No** ADA ID: AE9D3B9CEBD2 Ramp Type: Combination1 Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

No

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Ramp XSlope RT (%)

Data

68.0

60.0

5.8

3.4

48.0

54.0

N/A

Yes

To E

Flare Traversable LT?

Ramp XSlope LT (%)



Street 1 Name Signal **VALLEYDALE RD** Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A

"	i ossible solution			i ieiu ivie
-	Possible Solutions:	Compli	ance	Description
1	Remove & Replace Entire Ramp.	N/A	Ramp	Length LT (in)
	·	Yes	Ramp	Width LT (in)
		Yes	Ramp	Slope LT (%)
		No	Ramp	XSlope LT (%
The same		N/A	Ramp	Length (in)
1		Yes	Ramp	Width (in)
	Surveyor Notes:	N/A	Flare	Type LT
A STATE	RP < 5%	N/A	Flare	Slope LT (%)
		N/A	Flare	Traversable L1
Complete Co.		N/A	Landii	ng Length (in)
		N/A	Landii	ng Width (in)
	PROW/ADA:	N/A	Landii	ng Slope (%)
100	Not Found, R304.5.3, R304.3.2	N/A	Landii	ng X Slope (%)
		N/A	Landii	ng Curb? (Y/N
٦		N/A	Share	d Landing?
		N/A	Gutte	r Ponding?
		N/A	Gutte	Lip Ht (in)
		N/A	Painte	ed X Walk1?
			X Wal	k 1 Direction
			X Wal	k 1 Width (in)
			X Wal	k 1 Slope (%)

\$





Total Cost:



X Walk 1 Slope (%) X Walk 1 X Slope (%) X Walk 1 X Slope (%) X Walk 1 X Slope (%) X Walk 2 X
1800.00 N/A Ramp inside XWalk1? Yes Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A
Road Slope (%) Road X Slope (%) N/A N/A N/A Clear Space? N/A N/A N/A Any Obstruction? N/A
Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A
N/A Any Obstruction? N/A
Obstruction Type
N/A
N/A Storm Grate/Utility Hazard?
Storm Grate/Utility Type
N/A
Yes Surface Condition? (G/P) Good
Curb Slope (%) 11.6