

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16015 Main Street: ELLINGTON_ST Cross Street: WHEATLEY_AV Location: SW ADA ID: AEE8A32EE529 **Overall Compliance: No** Ramp Type: Perp Initial Pass/Fail: Pass **Severity Score:** 15

Codes/Mitigation Info/Possible Solution



ELLINGTON ST Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	2
Remove & Replace Entire Ramp.	N
Remove & Replace Gutter.	Y
	N
	1
	1
	1
Surveyor Notes:	1
N/A	1
	1
	1
	1
PROW/ADA:	١
Not Found, R304.2.1, R304.2.2-Perp,	Y
R304.3.2-Para, R304.5.3, R304.5.4	١
	ŀ

		1		
PROW/ADA:		!		
Not Found, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R304.5.4				
		I		
		ı		
Total Cost:	\$ 2600	.00		

VVIII.	
	Complete States
1	



Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	63.0	Yes	Ramp Slope (%)	5.2	
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.8	
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	5.1	Yes	Flare Slope RT (%)	0.3	
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes	
No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes	
No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes	
No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.5	
No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes	
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0	
N/A	Shared Landing?	No				
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	10.4	
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.8	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	Yes	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	

