

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		- /					
Intersection ID: 14724	Main Street: ALBEMARLE_RD			Cross Street: GUICE_CROSSING_LN				Location:	NW
ADA ID: AF11585D19A2	F11585D19A2 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	m- Charles	Possible Solutions:					ata Compliance Description		
and the second	the state of the s	Remove & Replace Entire Ra	nn.	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.1
	- B Contraction			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.7
	4			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ELVIN CONTRACTOR		2		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
And the second se				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
1 Mar Martin		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E.	C.F. Manuella			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
ALBEMARLE RD				N/A	Shared Landing?	N/A			
PROW/ADA:				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
the second second	- Ken	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the statement of	1 0.1			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GUICE CROSSING LN	-			X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

