

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18375	Main Street: MONTCLAIR_AV			Cross Street: WESTBURY_RD				Location:	SE
ADA ID: AF19754EEDEC	DEC Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description			Data	Data Compliance Description		
- Y	100	Remove & Replace Entire Ramp	. •	A/A	Ramp Length (in)	128.0	N/A	Grade Break?	N/A
3.1 1.	17			es	Ramp Width (in)	59.0	N/A	Grade Break Slope (%)	0.0
	CT T		Y	'es	Ramp Slope (%)	1.6	N/A	Grade Break XSlope (%)	0.0
	1- 0		Ν	lo	Ramp XSlope (%)	2.3			
A ARA	- Sia		N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	3 // A		Ν	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
Start Hon	Product 1	Surveyor Notes:	Ν	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	2	NO LNDG	Ν	I/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	AL AL		N	I/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
			N	I/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
MI In market	the state		N	I/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	and the second s	PROW/ADA:	N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	222	R304.5.3	Ν	I/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	and the		N	I/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
A	A ANDER		M	I/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
A VAL Y SEC	1 and and		N	I/A	Painted X Walk1?	No		Road Slope (%)	2.5
Street 1 Name Mo	ONTCLAIR AV				X Walk 1 Direction	To NE		Road X Slope (%)	2.2
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.2	N/A	Storm Grate/Utility Hazard?	N/A
			Ν	I/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			N	A/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	0.7

