


Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10024355 Main Street: CRESCENT EXECUTIVE DR Cross Street: N/A Location: NE **ADA ID: AF4597A761AB** Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



ENTRANCE Street 1 Name Stop Condition-Street 2 Street 2 Name **CRESCENT EXECUTIVE DR** Stop Condition-Street 1

Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

R304.5.3

None

Total Cost:

StopSign

Compliance Description Data		Comp	liance Description	Data	
N/A	Ramp Length (in)	108.0	Yes	Ramp Slope (%)	7.3
Yes	Ramp Width (in)	60.0	No	Ramp XSlope (%)	5.9
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	0.1
	X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	1.8
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.9	N/A	Clear Space?	N/A
	Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good







3200.00