cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-	-	-					
Intersection ID: 10021320 Main Street: BLAKENEY_GREENS_BV C					N/A	Location:	NW		
ADA ID: AF4A69897625 Ramp Type: PerpDiag I				tial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Characterian and	A COMPANY A COMPANY	Possible Solutions:				Data			Data
	5	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	51.0	No	Ramp Slope (%)	14.9
and the second s		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.9
M IS T >		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		-		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second second		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
BLAKENEY G	REENS DV	1/2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
TEFT	<u>હ</u> ં હે.			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
- Internal	197331	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	LIAN	1004.2.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To SE
and the set of	1-1-1-1			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name BLAKENEY GREENS BV					X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	4.5
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			10/4	Road Slope (%)	4.3	N/A	Clear Space?	N/A
	None				Road X Slope (%)	4.5 0.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.2 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00	197	Obstruction Type	10/4		Storm Grate/Utility Type	1975
		ψ	0200.00			N/A		Storm Orato/Otimey Type	N/A
						11/4			11/7

Yes Surface Condition? (G/P) Good

