

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 31207 Main Street: OAKTON_HUNT_DR			Cross	Cross Street: GOODLOE_DR				Location:	w
ADA ID: AF6186364556				Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
<u> </u>		Possible Solutions:					Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	6.6
		Two New Directional Ramps or		No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	0.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Contraction of the second seco				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name OAKTO	N HUNT DR	_			X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	2.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	1.9
Street 2 Name GC	OODLOE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.3	N/A	Clear Space?	N/A
					Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

