

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3302	Main Street: STATESVILLE_RD			Cross Street: METROMONT_PY				Location:	SE
ADA ID: B05994E02FFA	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	22.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Dat			a Compliance Description		Data
	Station (Remove & Replace Entire Ran	np.	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.4
Sector Sector	Read to a st	•	•	No	Ramp Width (in)	47.5	No	Ramp XSlope (%)	3.2
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A DESCRIPTION OF THE OWNER OWNER OF THE OWNER OWNER OF THE OWNER OWNE	ONER EN			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
MEUROM				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
<u>b.</u>	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
E.	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	e		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
PROW/ADA: R304.5.1, R304.2.2, R304.5.3				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ST	ATESVILLE RD				X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00)	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

