

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interrection ID: 22404								Lessting E	
Intersection ID: 23191	Main Street: ALEXANDER_RD			Cross Street: IRONKETTLE_RD				Location: E	
ADA ID: B0853B617427 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	3	Possible Solutions:	Compliance Description			Data	Data Compliance Description		
the second se	Charles Mar	Remove & Replace Entire Ramp.	N/.	Α	Ramp Length (in)	49.0	No	Ramp Slope (%)	10.6
allor I and	and the same		Ye	es	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.9
	The attress		N//	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E State	ET al		N/	Ά	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	E Stand		N/	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A CAR	Surveyor Notes:	N/	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
and the		N/A	N/	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A LANDER OF	Contraction of the second		N/	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
AD A	and the		N/	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A REAL PROPERTY AND A REAL			N/	Α	Shared Landing?	N/A			
	Tearing 1	PROW/ADA:	N/	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2	N//	Ά	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
No State And			N/.	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
			N/	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ONKETTLE RD	_			X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/	Α	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/	/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good



