cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27422 Main Street: BALLANTYNE_COMMONS_PY Cross Street: STONEBRIAR_DR									SW	
ADA ID: B0A39FA9					Initial Pass/Fail: Fail Overall Compliance: No					
Codes/Mitigation Info/Possible Solution					Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75 Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Entire Ram).	N/A	Ramp Length (in)	43.0	No	Ramp Slope (%)	9.6	
				Yes	Ramp Width (in)	51.0	Yes	Ramp XSlope (%)	2.3	
	6 6 9			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	L C L			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
BALLANTYNE COM	MONS PY			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
J y				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
And I Constant of the Statement		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
the stands				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
PROW/ADA: Not Found, R304.2.2				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name BALLANTYNE COMMONS PY					X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	



