## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10014544	ntersection ID: 10014544 Main Street: BROOKSIDE_LN Cross Street: N/A							Location:	NW	
ADA ID: B0CCB269D57B Ramp Type: PerpDiag			Initial P	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	d.	Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Curb Ramp W	lith	N/A	Ramp Length (in)	72.5	Yes	Ramp Slope (%)	6.7	
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	10.5	
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Pol Land -				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
A BAR AN				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
E.		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
EROOKSIDE				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
- State - Stat				N/A	Shared Landing?	N/A				
AND PARAMETERS		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	A COMPANY - P	1949			X Walk 1 Direction	To S		X Walk 2 Direction	To E	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	0.8	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (%)	5.1	
Street 2 Name	BROOKSIDE_LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign				Road Slope (%)	2.7	N/A	Clear Space?	N/A	
	-				Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

**Yes** Surface Condition? (G/P)

Good

