

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21814 Main Str	Main Street: D_DUCKS_LN		Cross Street: WESTINGHOUSE_BV				Location:	NE
ADA ID: B0DC25092707 Ramp Ty	amp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
ES WESTINGLIOUSELED	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
	Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	8.6
	Two New Directional Ramps or		No	Ramp Width (in)	45.5	No	Ramp XSlope (%)	2.4
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name D DUCKS LN				X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	0.3
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	4.3
Street 2 Name WESTINGHOUSE BV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	0.7	N/A	Clear Space?	N/A
				Road X Slope (%)	5.2	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

es Surface Condition? (G/P)

Good

