

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                         |                             |                        |
|------------------------|-------------------------|-----------------------------|------------------------|
| Intersection ID: 17494 | Main Street: MONROE_RD  | Cross Street: FOREST_WAY_DR | Location: NE           |
| ADA ID: B0E4774F828E   | Ramp Type: Directional1 | Initial Pass/Fail: Pass     | Overall Compliance: No |
|                        |                         | Severity Score: 0           |                        |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Landing.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.2.2-Perp, R304.3.2-Para**

| Compliance | Description           | Data  | Compliance | Description                 | Data |
|------------|-----------------------|-------|------------|-----------------------------|------|
| N/A        | Ramp Length (in)      | 90.0  | Yes        | Grade Break?                | Yes  |
| Yes        | Ramp Width (in)       | 69.0  | Yes        | Grade Break Slope (%)       | 5.0  |
| Yes        | Ramp Slope (%)        | 4.0   | Yes        | Grade Break XSlope (%)      | 1.6  |
| Yes        | Ramp XSlope (%)       | 0.6   |            |                             |      |
| Yes        | Flare Type LT         | N/A   | Yes        | Flare Type RT               | N/A  |
| N/A        | Flare Slope LT (%)    | N/A   | N/A        | Flare Slope RT (%)          | N/A  |
| N/A        | Flare Traversable LT? | No    | N/A        | Flare Traversable RT?       | No   |
| Yes        | Landing Length (in)   | 85.0  | Yes        | DWS Provided?               | Yes  |
| Yes        | Landing Width (in)    | 69.0  | Yes        | DWS Contrast?               | Yes  |
| No         | Landing Slope (%)     | 2.4   | Yes        | DWS Length (in)             | 24.0 |
| Yes        | Landing X Slope (%)   | 1.5   | Yes        | DWS Full Width?             | Yes  |
| N/A        | Landing Curb? (Y/N)   | No    | Yes        | DWS Offset LT (in)          | 6.0  |
| N/A        | Shared Landing?       | Yes   | Yes        | DWS Offset RT (in)          | 2.0  |
| Yes        | Gutter Ponding?       | No    | Yes        | Gutter Slope (%)            | 4.9  |
| Yes        | Gutter Lip Ht (in)    | 0.0   | Yes        | Gutter X Slope (%)          | 1.4  |
| N/A        | Painted X Walk1?      | No    |            | Road Slope (%)              | 3.2  |
|            | X Walk 1 Direction    | To SW |            | Road X Slope (%)            | 1.6  |
|            | X Walk 1 Width (in)   | N/A   |            | Clear Space?                | Yes  |
|            | X Walk 1 Slope (%)    | 3.2   | N/A        | Clear Space to XWalk (in)   | N/A  |
|            | X Walk 1 X Slope (%)  | 1.6   | Yes        | Storm Grate/Utility Hazard? | No   |
| N/A        | Ramp inside XWalk1?   | N/A   |            | Storm Grate/Utility Type    |      |
| Yes        | Any Obstructions?     | No    |            |                             | N/A  |
|            | Obstruction Type      |       | Yes        | Surface Condition? (G/P)    | Good |
|            |                       |       | N/A        | Curb Slope (%)              | 5.1  |

Total Cost: \$ 500.00

|                         |           |
|-------------------------|-----------|
| Street 1 Name           | MONROE RD |
| Stop Condition-Street 1 | None      |
| Street 2 Name           | N/A       |
| Stop Condition-Street 2 | N/A       |

