

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10033483 Main Street: OLD\_PINEVILLE\_RD Cross Street: N/A Location: NW **Overall Compliance: No Severity Score: ADA ID: B12B7BEA4230** Ramp Type: Directional1 Initial Pass/Fail: Fail 1.25

**Codes/Mitigation Info/Possible Solution** 



**ENTRANCE** Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

Possible Solutions:
Remove & Replace Entire Ramp.
Surveyor Notes:
N/A
PROW/ADA:
R304.5.3
i

Automation of the Control of the Con	
1	



Total Cost:



1600.00

Field Measurements/Component Compliance							
Compli	ance Description	Data	Compli	ance Description	Data		
N/A	Ramp Length (in)	68.0	N/A	Grade Break?	N/A		
Yes	Ramp Width (in)	67.0	N/A	Grade Break Slope (%)	0.0		
Yes	Ramp Slope (%)	4.2	N/A	Grade Break XSlope (%)	0.0		
No	Ramp XSlope (%)	3.8					
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes		Road Slope (%)	4.1		
	X Walk 1 Direction	То Е		Road X Slope (%)	3.2		
	X Walk 1 Width (in)	88.0		Clear Space?	N/A		
	X Walk 1 Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A		
	X Walk 1 X Slope (%)	3.2	N/A	Storm Grate/Utility Hazard?	N/A		
N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type			
N/A	Any Obstructions?	N/A			N/A		
	Obstruction Type		Yes	Surface Condition? (G/P)	Good		
		N/A	N/A	Curb Slope (%)	6.5		