

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

				Croco	Cáro of		Location			
Intersection ID: 10180	Main Street: FERN_AV			Cross	Street:	TUCKASEEGEE_R	Location:	NW		
ADA ID: B1360DEABD19 Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	49-18	Possible Solutions:			Compliance Description			Data Compliance Description		
	Kein	Remove & Replace Entire F	Ram	р.	N/A	Ramp Length (in)	50.0	Yes	Ramp Slope (%)	6.5
	11.4	-			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.0
a te stal the	16 -				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Property				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Stan And Martin	10 1				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	LI				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	202	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 P	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
GRADE	8.20				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E.	Carla 2				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A CARACTER AND					N/A	Shared Landing?	N/A			
6.	-30	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
14 The second states of	and the state	Not Found, R304.5.3			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
to the second which	Ser and	,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	6					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
	and the				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	FERN AV					X Walk 1 Slope (%)	7.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	8.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

