

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49197 Main Street: GRAYPARK DR Cross Street: ALEXANDER FOREST DR Location: S **Severity Score:** ADA ID: B13E9466E392 Ramp Type: PerpDiag Initial Pass/Fail: Pass **Overall Compliance: No** 7.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



ALEXANDER FOREST DR Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

None

StopSign

GRAYPARK DR

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.2.1, R305.2, R302.7.2

Total Cost: 3200.00 Compliance Description Data Compliance Description Data Yes Ramp Slope (%) N/A Ramp Length (in) 48.0 6.5 48.0 No Ramp XSlope (%) Yes Ramp Width (in) 2.6 N/A N/A Flare Type LT Sloped Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) 1.6 7.4 N/A Flare Traversable LT? Nο N/A Flare Traversable RT? Nο No Landing Length (in) 45.5 Yes DWS Provided? Yes Yes Landing Width (in) 48.0 Yes **DWS Contrast?** Yes Yes Yes Landing Slope (%) 0.6 DWS Length (in) 24.0 Yes Landing X Slope (%) 1.9 Yes DWS Full Width? Yes N/A Landing Curb? (Y/N) No No DWS Offset (in) 4.0 N/A Shared Landing? No **Gutter Ponding?** No Yes Gutter Slope (%) Yes 3.0 No Gutter Lip Ht (in) 0.5 Yes Gutter X Slope (%) 1.3 N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To NE X Walk 2 Direction To NW N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 1.7 X Walk 2 Slope (%) 3.0 X Walk 1 X Slope (%) 3.6 X Walk 2 X Slope (%) 1.9 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 0.5 N/A Clear Space? Yes N/A Road X Slope (%) 4.7 Clear Space to XWalk (in) N/A No Yes Any Obstructions? Yes Storm Grate/Utility Hazard? No **Obstruction Type** Storm Grate/Utility Type N/A N/A

Yes

Surface Condition? (G/P)

Good





