

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7104 Main Street: AERIAL_CT					Cross Street: KINGVILLE_DR					Location:	SE	
ADA ID: B15523AEBB27	Ramp Ty	/pe: Combination2		I	nitial Pass/Fa	ail: Fail	Overall Com	npliar	nce: N	o Severity Score:	50	
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
Possible Solutions:					Compliance Description			Data Compliance Description			Data	
		Remove & Replace Er	ntiro Ra	mn	N/A	Ramp Lengtl		N/A		Ramp Length RT (in)	12.0	
				mp.	N/A	Ramp Width		N/A	Yes	Ramp Width RT (in)	48.0	
					N/A	' Ramp Slope		N/A		Ramp Slope RT (%)	12.0	
	AND DE				N/A	Ramp XSlop			No	Ramp XSlope RT (%)	6.8	
					N/A	Ramp Lengtl		53.0	Yes	Ramp Slope (%)	7.3	
					Yes	Ramp Width		48.0	No	Ramp XSlope (%)	7.7	
	T	Surveyor Notes:			N/A	Flare Type L	T	N/A	N/A	Flare Type RT	N/A	
		CRACK LT FL, CURB GAP 1.0"			N/A	Flare Slope	LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Travers	sable LT?	N/A	N/A	Flare Traversable RT?	N/A		
				N/A	Landing Len	gth (in)	N/A	N/A	DWS Provided?	N/A		
				N/A	Landing Wid	th (in)	N/A	N/A	DWS Contrast?	N/A		
		PROW/ADA:			N/A	Landing Slop	pe (%)	N/A	N/A	DWS Length (in)	N/A	
	and the second second	Not Found, R304.5.3, R304.3.2			N/A	Landing X SI	lope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curl	b? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
					N/A	Shared Land	ling?	N/A				
	1. 1.				N/A	Gutter Pond	ing?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	StopSign				N/A	Gutter Lip H	t (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	AERIAL CT				N/A	Painted X W	alk1?	No	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Dir	ection	To N		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Wie	dth (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slo	ope (%)	1.9		X Walk 2 Slope (%)	N/A	
						X Walk 1 X S	Slope (%)	3.4		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1600	.00 N/A	Ramp inside	XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope	(%)	N/A		Clear Space?	N/A	
						Road X Slop	e (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			-						N/A	Any Obstruction?	N/A	
	Pat		- Com							Obstruction Type		

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good

Curb Slope (%)

N/A

29.7