

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 8181 Main Street: FREEDOM_DR Cross Street: TODDVILLE_RD Location: SW

ADA ID: B166EA0DCD95 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Total Cost:

Field Measurements/Component Compliance

Compliance Description

Data



THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IN COLUMN	
Street 1 Name	TODDVILLE RD
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

1 OSSIDIE OCIALION		i icia ivic
Possible Solutions:	Comp	liance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	Yes	Ramp Width (in)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
	N/A	Flare Traversable LT
	N/A	Landing Length (in)
Surveyor Notes:	N/A	Landing Width (in)
N/A	N/A	Landing Slope (%)
	N/A	Landing X Slope (%
	N/A	Landing Curb? (Y/N
	N/A	Shared Landing?
PROW/ADA:	N/A	Gutter Ponding?
Not Found, R304.2.2	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
	N/A	X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%

The second second



1850.00

No Ramp Length (in) 84.0 Ramp Slope (%) 8.4 Yes Ramp XSlope (%) Ramp Width (in) 48.0 0.0 es N/A Flare Type LT N/A Flare Type RT N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A /A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A Α /A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A /A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? Gutter Ponding? N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? Yes N/A Painted X Walk2? N/A X Walk 1 Direction To NW X Walk 2 Direction N/A X Walk 1 Width (in) 112.0 X Walk 2 Width (in) N/A X Walk 1 Slope (%) 0.7 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 0.3 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A Ramp inside XWalk2? Yes N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A Any Obstructions? N/A N/A N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good