cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

Intersection ID: 27245 Main Street: ELMSTONE_DR					Location:	S		
			Cross Street: THORNCREST_RD					
ADA ID: B1E5825642A3 Ramp Type: PerpDiag		Initial Pas	Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
5	Possible Solutions:	<u>c</u>	Compliance Description			ata Compliance Description		
	Remove & Replace Curb Ramp	With N	/ A	Ramp Length (in)	36.0	No	Ramp Slope (%)	8.7
	Two New Directional Ramps or	Y	es	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.6
	Equivalent.	N	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	and the second se	N	/ A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Same and the second	N	/ A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
THE PART OF A STATE	THE N	N	/ A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
STOLE B	Surveyor Notes:	N	/ A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
5	N/A	N	/ A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		Ν	/ A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N	/ A	Shared Landing?	N/A			
	PROW/ADA:	Ν	/ A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A la share the state	Not Found, R304.2.2, R304.5.3	N	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second second		Ν	/ A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
the state of the second states				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
	e.	Ν	/ A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name THORNCRE	EST RD			X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	4.5
Stop Condition-Street 2 Sto	opSign			X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	2.1
Street 2 Name ELMSTO	NE DR	Ν	/ A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			Road Slope (%)	2.4	N/A	Clear Space?	N/A
				Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
		N	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

