


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 21044	Main Street: PARK_SOUTH_DR	Cross Street: ROUND_OAK_RD	Location: SE
ADA ID: B1F58B4566C6	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Street 1 Name

ROUND OAK RD

Stop Condition-Street 1

StopSign

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.2.2

Total Cost:

\$

1600.00

Compliance		Description	Data	Compliance		Description	Data
N/A	Ramp Length (in)	134.0	N/A	Grade Break?	N/A		
No	Ramp Width (in)	40.0	N/A	Grade Break Slope (%)	0.0		
No	Ramp Slope (%)	10.2	N/A	Grade Break XSlope (%)	0.0		
Yes	Ramp XSlope (%)	1.9					
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No		Road Slope (%)	0.1		
	X Walk 1 Direction	To N		Road X Slope (%)	3.7		
	X Walk 1 Width (in)	N/A		Clear Space?	N/A		
	X Walk 1 Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A		
	X Walk 1 X Slope (%)	3.7	N/A	Storm Grate/Utility Hazard?	N/A		
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
N/A	Any Obstructions?	N/A			N/A		
	Obstruction Type		Yes	Surface Condition? (G/P)	Good		
		N/A	N/A	Curb Slope (%)	9.3		

