

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		Υ.	. ,						
Intersection ID: 44779	Intersection ID: 44779 Main Street: AYRSLEY_TOWN_BV		Cross Stree	et: SILVER_CRESCENT	Location:	w			
ADA ID: B2055B3D8909	BD8909 Ramp Type: BlendTrans1		Initial Pass	nitial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	600	Possible Solutions:	Cor	Compliance Description		ata Compliance Description		Data	
1 1 a 52 G		Remove & Replace Curb Ramp W	ith N/A	Ramp Length (in)	97.0	Yes	BlendTrans Slope (%)	4.2	
		Two New Directional Ramps or Equivalent.	Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	3.6	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
11 23 56 10			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:	N/A		N/A	N/A	DWS Contrast?	N/A	
		N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A		N/A	N/A	DWS Full Width?	N/A	
			N/A	3 • • • <i>i</i> • <i>i</i>	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A		. ,		
		PROW/ADA:	N/A	•	N/A	N/A	Gutter Slope (%)	N/A	
		R304.5.3	N/A	-	N/A	N/A	Gutter X Slope (%)	N/A	
		1004.0.0	N/A	1 ()	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	AYRSLEY TOWN BV	-		X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	StopSign			X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A		N/A	,	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A			Road Slope (%)	1.8		Clear Space?	N/A	
• *				Road X Slope (%)		N/A	Clear Space to XWalk (in)	N/A	
			N/A	, ,		N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 320	00.00	Obstruction Type			Storm Grate/Utility Type		
		•	-	<i>,</i> ,	N/A			N/A	
						1			

YesSurface Condition? (G/P)N/ACurb Slope (%)

Good

1.0





