## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



									Lander		
Intersection ID: 9561	Main Street: SELDON_DR			Cross	Cross Street: W_TRADE_ST				Location:	E	
ADA ID: B21B8F499B16	Ramp Type: Perp			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	46.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	1 12 1	Possible Solutions:			Compliance Description			Data Compliance Description			
CAN AN ALLAND		Remove & Replace E	ntire Ram	р.	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	9.2	
	1	-			No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	7.6	
	and and				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Sort -	A AND				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
ST	the last				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	16 3.	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	Marcal				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	1 夏二分				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	2 Mar			N/A	Shared Landing?	N/A					
	- AND	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	1 Aller	Not Found, R304.5.1,	R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A	
a start and a start and a start a star		R304.5.3			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
MARCE / CARRIER				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	SELDON DR					X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	7.7		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

Yes Surface Condition? (G/P)

Good

