## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: N/A	A Main Street: LAWYERS_RD		Cross Street: MCALPINE_GLEN_DR				Location:	SW	
ADA ID: B29AC90A908A	AC90A908A Ramp Type: PerpDiag		Initial F	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Compliance Description Data					
A CARDON		Remove & Replace Curb Ramp W	Nith	N/A	Ramp Length (in)	110.5	1	Ramp Slope (%)	8.6
	States and the	Two New Directional Ramps or	VILII	No	Ramp Width (in)	44.5	Yes	Ramp XSlope (%)	0.9
	A ANDER STATE	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the the Bar				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
4. Martin				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
CONTRACT OF THE OWNER	The Aven			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 Com			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A N/A
		N/A			<b>0</b> 1 ( )			<b>o</b> ( )	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	The second			N/A	Shared Landing?	N/A			
	These and	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A	Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1 aller			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
To State 1					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
IS ALL IN IL	10%			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	MCALPINE GLEN DR				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	0.1
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	2.8
Street 2 Name	LAWYERS RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.8	N/A	Clear Space?	N/A
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
		•••••••••••••••••••••••••••••••••••••••				N/A			N/A
						11/4			11/2