

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

100.0

72.0

8.8

1.7

8.1

2.4

N/A

N/A

N/A

N/A

N/A

N/A

10.1

Intersection ID: 10224 Main Street: HERRIN_AV Cross Street: SPENCER_ST Location: NE

ADA ID: B2EDDED2A4C1 Ramp Type: Combination2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

N/A

N/A

N/A

N/A

Yes

N/A

N/A

N/A

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

Curb Slope (%)

Flare Traversable RT?

Flare Type RT

Data

N/A

N/A

N/A

N/A

94.0

48.0

N/A

N/A

N/A

N/A

N/A



Street 1 Name
StopSign
Stop Condition-Street 1
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:						
Remove & Replace Entire Ramp.						
·						
Surveyor Notes:						
N/A						
PROW/ADA:						
Not Found, R304.5.3, R304.3.2						



Total Cost:



1600.00

N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
and the same				Obstruction Type	
					N/A
-			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
					N/A
			Yes	Surface Condition? (G/P)	Good

