

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

20.0

60.5

12.1

5.3

11.3

2.7

N/A

Main Street: N CHURCH ST Intersection ID: 9919 Cross Street: W 28TH ST Location: W Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** ADA ID: B342A66CFF4E Ramp Type: Combination1 72.5

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

Yes

No

No

No

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Data

37.0

59.0

7.0

4.1

60.5

27.0

N/A

No

To N

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign N CHURCH ST Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes Yes No N/A No Surveyor Notes: N/A **GTR LIP 1.5** N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.2.2, N/A R304.5.3, R304.3.2 N/A N/A N/A N/A N/A

Total Cost:



		A Trail   Diroction			A Trail E Bilocuon	
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	5.7		X Walk 2 Slope (%)	N/A
		X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A
1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstruction?	N/A
					Obstruction Type	
						N/A
	and the second			N/A	Storm Grate/Utility Hazard?	N/A
					Storm Grate/Utility Type	IV/A
						N/A
				Yes	Surface Condition? (G/P)	Good
					Curb Slope (%)	32.6
The state of the s	The state of the s					

