

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

ntersection ID: N/A Main Street: BALLANTYNE_COMMONS_PY Cross Street: N/A								Location:	SW	
ADA ID: B34DBBC1C528 Ramp Type: Perp					Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	21.25
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		
	1. 100	Remove & Replace Entire	Ramp	).	N/A	Ramp Length (in)	73.0	No	Ramp Slope (%)	8.8
			•		No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	0.1
and the second second	in .				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
THE P					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
CONTRACTOR		-			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
BALLANDAL	W. A.				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
- Charles - Char	S.	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
t.	1 grand the	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Contraction of the second second					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second	11				N/A	Shared Landing?	N/A			
	MED.	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R30	4.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
The Allow	MAK	· · ·			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
LARDEN SIL						X Walk 1 Direction	To E		X Walk 2 Direction	N/A
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE					X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A