cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · ·									
Intersection ID: 15849	Main Str	Main Street: NORTON_RD			Cross Street: QUEENS_RD_WEST				NE
ADA ID: B354C2121101	Ramp Ty	Ramp Type: PerpDiag			ail: Fail Overall (o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
1 Mark		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	83.0	Yes	Ramp Slope (%)	6.4
		Two New Directional Ramps or		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	3.5
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Se - 200 7 19			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
and the second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A CALL AND A CALL				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
120		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A A A A A A A A A A A A A A A A A A A		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A A A A A A A A A A A A A A A A A A A		1071		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	JI / I			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second s	The states	PROW/ADA:		N/A	Shared Landing?	N/A			
TEALER	1 200			N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
COL E		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		Not i build, R304.5.1, R304.5.5		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	1 2 1 1 martin				X Walk 1 Direction	To W		X Walk 2 Direction	To S
	2 M 1 2 - 5 1			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	NORTON RD			10/4	X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	3.2
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.7 1.8		X Walk 2 X Slope (%)	3. <u>2</u> 1.1
Street 2 Name	QUEENS RD WEST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			11/4	Road Slope (%)	2.1	N/A	Clear Space?	N/A
Stop Condition-Street 1	None								
					Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
		Table of		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type	•••-		Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

